# Oil Field Environmental Incident Summary

Incident: 20150925120833 **Date/Time of Notice:** 09/25/2015 12:08 Responsible Party: SECURE ENERGY SERVICES USA, LLC SECURE ENERGY SERVICES USA, LLC Well Name: 13 MILE SWD 1 Field Name: TYRONE Well File #: 90159 Date Incident: 9/24/2015 Time Incident: 13:19 Facility ID Number: **WILLIAMS** Rna: 101 Sec: 12 Qtr: County: **Twp:** 156 **Location Description:** pipeline shack Submitted By: chris murphy Received By: Contact Person: josh mosbrucker 555 17TH ST STE 800 DENVER, CO 80202-3908 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Valve/Piping Connection Leak Release Contained in Dike: Yes - On Facility Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** Oil **Brine Barrels** Barrels Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

no risk health wize got it cleaned up very fast

Areal Extent:

### Potential Environmental Impacts:

vac truck was onsite in 30 min of spill clean it very fast

### Action Taken or Planned:

vac truck was onsite within 30 min of spill cleaning up the spill contaminated soil was removed and disposed of on site

Wastes Disposal Location:

Agencies Involved:

## **Updates**

Date: 9/28/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.